02975.000120 PATENT

# IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	
KAISHI OHASHI, ET AL.	:	Examiner: Thomas M. Dougherty
Appl. No.: 10/725,510	:	Group Art Unit: 2834
Filed: December 3, 2003	: )	Confirmation No.: 5015
For: VIBRATION TYPE DRIVING	:	
APPARATUS	:	
U.S. Patent No.: 7,034,438 B2	;	
Issued: April 25, 2006	)	June 19, 2007

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

# REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form (Form PTO-1050) is enclosed.

No fee is believed to be due with the filing of this Certificate of Correction. However, the Commissioner is authorized to charge any fee deemed necessary by the filing of this paper to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Mark A. Williamson/

Mark A. Williamson Attorney for Patentees Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800

Facsimile: (212) 218-2200

MAW:eyw

Form #33 - 2 -

# UNITED STATES PATENT AND TRADEMARK OFFICE. CERTIFICATE OF CORRECTION

PATENT NO. : US 7,034,438 B2

DATED : April 25, 2006

INVENTOR(S) : OHASHI, ET AL. Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# ON THE TITLE PAGE, AT ITEM (56) References Cited:

U.S. Patent Documents, "6.559.574 B1" should read --6.559.574 B2--.

# COLUMN 1:

Line 29 "electromechanical" should read --electro-mechanical--

# COLUMN 4:

Line 28, "piezo electric" should read --piezoelectric--.

Line 63, "Dower" should read -- power--.

# COLUMN 7:

Line 43, "side)" should read --side).--.

#### COLUMN 11:

Line 40, After "Embodiment 1." a new heading -- Embodiment 2-- should be inserted.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) FCHS\_WS 1410686 v1

PATENT NO. US 7,034,438 B2

No. of add'l. copies @ 30¢ per page



# Staple Here Only! NEL S. BELINER

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 7,034,438 B2

DATED : April 25, 2006

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# COLUMN 13:

INVENTOR(S) :

Line 60, "steed" should read -- speed --.

OHASHI, ET AL.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Fassimile

PATENT NO. US 7,034,438 B2

No. of add'l. copies @ 30¢ per page

